




SELF MEASUREMENT GUIDE

WILDLAND JACKET
J864-GLD



FOLLOW THE MEASUREMENT GUIDE BELOW TO DETERMINE YOUR GARMENT SIZE

A - Measure your chest circumference directly under your arms

All measurements are in CM

SIZES	77	82	87	92	97	102	107	112	117
A - Chest	75-80	80-85	85-90	90-95	95-100	100-105	105-110	110-115	115-120